

25X

OUT 65594

BT  
CONFIDENTIAL

CITE NPIC 4242.

## PART I. SIGNIFICANT PHOTO INTERPRETATIONS

## B. NEW TARGETS AND SIGNIFICANT CHANGES

ZZZ01:DONG PHONG THUONG RR BY-PASS SGM R4D CTY VN 195800N1054938E  
TWO RAIL BY-PASS BRIDGES ARE BEING RECONSTRUCTED ACROSS THE SONG  
LAU (RIVER) 1.2 NM WEST OF THE DESTROYED DONG PHONG THUONG RAIL  
AND HIGHWAY BRIDGE. PIERS HAVE BEEN REPLACED TO ACCOMMODATE THE  
WESTERNMOST BRIDGE. THE APPROACHES TO EACH OF THESE BY-PASSES  
HAVE BEEN CLEARED AND GRADED. NEW RAIL IS BEING LAID ON THE  
NORTHERN APPROACH TO THE WESTERN BRIDGE. DECK SPANS, PROBABLY  
FOR THESE BRIDGES, ARE BEING ASSEMBLED ON THE RAIL BY-PASS  
APPROXIMATELY 500 METERS SOUTH OF THE CROSSING SITE. THIS SPAN  
CONSTRUCTION IS BEING FACILITATED BY A CANTILIVER RAIL CRANE AT  
THE SITE OF THE SPAN ASSEMBLY (UTM WH863073). ADDITIONAL  
BRIDGING AT THE DONG PHONG THUONG CROSSING INCLUDES ONE SERVICE  
AND ONE UNSERVICEABLE RAIL BY-PASS BRIDGE EAST OF THE DESTROYED  
DONG PHONG THUONG RAIL AND HIGHWAY BRIDGE AND TWO PONTOON AND  
ONE CABLE HIGHWAY BRIDGE WEST OF THE DESTROYED BRIDGE.

PART II. OTHER PHOTO INTERPRETATIONS - NONE  
GP-1

C O N F I D E N T I A L

END OF MESSAGE

Declassification review by  
NGA

25x1

25x1

GROUP 1  
Excluded from automatic  
downgrading and  
declassification